

CHESHIRE INLAND WETLANDS AND WATERCOURSES COMMISSION
SITE WALK:

CORNWALL AVENUE

SATURDAY, FEBRUARY 24, 2018

SITE WALK BEGAN AT 9:00 A.M.

Members Present: Charles Dimmick, Kerrie Dunne, Thom Norback and Will McPhee

Others Present: Suzanne Simone, Commission Staff
Jason Bartlett, Property Owner
David Lord, Soil Scientist (representing Mr. Bartlett)
Neighbor

Commission members walked the west side of the pond and observed exposed soil along and within the pond. Mr. Bartlett and Mr. Lord identified the "original" edge of the pond. The extent of the fill within the pond was observed.

Mr. Barlett identified the area of water discharge and located prior neighbor flooding issues as a result of occasions when the pond discharge flowed outside the designated swale.

Silt fence was observed, installed perpendicular to the drainage swale. Ms. Simone asked Mr. Barlett to monitor and maintain this erosion control, which serves to hold back sediment from the unsecured fill piles within the pond, as the water drains into the stone lined swale.

The site walk of this property concluded at 9:20 a.m.