

The site walk of 129 Mountain Brook Road started at 0900 am and ended at 0930 am on December 11, 2021. Weather was 52 F and light rain.

Commissioners present were: Dr. Charles Dimmick, Will McPhee, Thom Norback, and Tim Graver

Michael J. Strollo, Cheshire Zoning Enforcement Officer, was also present

Also present were David Onorfrío, site owner, and David Lord, Certified Soil Scientist & Environmental Consultant

We walked up the hill to the house building site and further past the site to observe the areas of concern. David Lord gave his description of the area as also identified in his report dated November 29, 2021.

The site walk of 135 Mountain Brook Road started at 0930 am and ended at 0943 am on December 11, 2021. Weather was 52 F and drizzle.

Commissioners present were: Dr. Charles Dimmick, Will McPhee, Thom Norback, and Tim Graver

Michael J. Strollo, Cheshire Zoning Enforcement Officer, was also present

Also present was Holly Harte, home owner of 135 Mountain Brook Road

We walked along the retaining wall and through the back of the property. Holly Harte described the flow of water during the past storm events and both showed and described the damage that occurred.